


136015_3_2.JPG: HR1954, test set-up fully anechoic chamber

Examiner: Thomas KÜHN
Date of issue: 30 October 2014 Test Report No.: F136015E4, 3rd version Order No.: 13-116015

page 1 of 6





136015_3_10.JPG: HR1954, test set-up fully anechoic chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F136015E4, 3rd version

 Date of issue:
 30 October 2014
 Order No.:
 13-116015
 page 2 of 6






136015_3_11.JPG: HR1954, test set-up fully anechoic chamber

Examiner: Thomas KÜHN
Date of issue: 30 October 2014 Test Report No.: F136015E4, 3rd version Order No.: 13-116015

page 3 of 6





136015_3_12.JPG: HR1954, test set-up fully anechoic chamber

Examiner: Thomas KÜHN
Date of issue: 30 October 2014 Test Report No.: F136015E4, 3rd version Order No.: 13-116015

page 4 of 6



page 5 of 6

ANNEX A: TEST SET-UP PHOTOGRAPHS



136015_3_16.JPG: HR1954, test set-up open area test site

Examiner: Thomas KÜHN Test Report No.: F136015E4, 3rd version
Date of issue: 30 October 2014 Order No.: 13-116015



page 6 of 6

ANNEX A: TEST SET-UP PHOTOGRAPHS



136015_3_13.JPG: HR1954, test set-up shielded chamber

 Examiner:
 Thomas KÜHN
 Test Report No.:
 F136015E4, 3rd version

 Date of issue:
 30 October 2014
 Order No.:
 13-116015