

**Tom Cokenias**

---

**From:** W Li [weili@ac-lab.com]  
**Sent:** Monday, August 13, 2007 7:43 PM  
**To:** Tom Cokenias  
**Subject:** Re: Remote Play Inc., FCC ID: ST2-IT100, Assessment NO.: AN07T7082, Notice#1

PLEASE SEE MORE ANSWERS TO YOUR QUESTIONS:

REGARDS,

WEI

*TCokenias@ccsemc.com* wrote:

Dear Wei Li,

I have been assigned to review your application. The following items must be addressed before processing may proceed:

1. Per section 2.1033(b)5 of the Rules, please supply a block diagram showing the frequencies of all oscillators

PLEASE SEE REVISED BLOCK DIAGRAM.

2. The test report seems to indicate that AC line conducted testing was performed in the receive mode only. Section 15.207 requires AC line conducted emissions testing to be performed for the transmitter section as well. Please comment, and if necessary supply a revised test report containing the required measurement for the transmitter portion of this product

PLEASE SEE REVISED REPORT SENT TO YOU LAST TIME.

3. Page 6 of the test report shows Last Cal dates that have not yet occurred. Please submit a revised report with the correct calibration dates.

OLD DATE FORMAT: D/M/Y.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

**Tom Cokenias**

---

**From:** W Li [weili@ac-lab.com]  
**Sent:** Monday, August 13, 2007 7:41 PM  
**To:** Tom Cokenias  
**Subject:** Re: Remote Play Inc., FCC ID: ST2-IT100, Assessment NO.: AN07T7082, Notice#2

PLEASE SEE ATTACHED FILES AND ANSWERS.

REGARDS,

WEI

*Tokens@cosmic.com* wrote:

Dear Wei Li,

The following items were accidentally left off of the previous request. These additional items must also be addressed before processing can continue.

1. It appears this application is for a device operating under the requirements of 15.249 of the Rules. Please confirm or correct.

YES. IT'S FOR 15.249.

2. Please provide an attestation letter justifying your request to wit hold internal photos from public view. Normally internal photos are not kept confidential, unless the circuits are potted or if the installation is such that the product is not easily accessible (e.g., tower mounted transmitters). PLEASE SEE REVISED CONFIDENTIALITY LETTER. NO CONFIDENTIALITY REQUEST FOR INTERNAL PHOTOS FOR IT100.

3. 15.249(d) requires all emissions outside the specified frequency bands to be at least 50 dB below the level of the fundamental, or at the general radiated emissions limit levels in 15.209. Please provide plots or radiated data showing compliance to this requirement at the highest and lowest operating channels.

PLEASE SEE REVISED REPORT. NO SIGNIFICANT SPURIOUS WERE FOUND FOR IT100 TX MODE.

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.