



SNC CO., LTD.

TEL : +82-31-420-5892

FAX: +82-31-420-5899

www.snclcd.co.kr

Sungjin Neotech Co. , Ltd. Rm. 401, Megavally 799,
Kwan yang-Dong, Dong an-Gu, An yang-Si, Gyeonggi-Do, Korea

Date	2006. 07. 10	Ref.No	QD-QA-0607-001
To	FCC	Fax.No	+
ATTN.			
Cc.	Timco Engineering Inc.		
FROM	SNC CO., LTD.		
TITLE	Reason of Modification	Page	1/1

Dear Sir,

Following is the reason of modification for our LCD MONITOR MV190F and MV177S.

1. Chipset changed

The old chipset (Realtek chipset "RTD 2022, 2522) couldn't production any more from manufacture. So, we must be change by new chipset. The new chipset is the "TSUM56AL" of M-star.

2. Changed Material of PCB Board against of RoHS

We applied by the PBFree material for PCB board against of RoHS.
The applied PCB board is AD board and OSD board Inverter Board.

SNC Co., Ltd.
Chief Executive Officer
Sundance Jeong

CO., LTD.