



February 21, 2012

Federal Communications Commission  
Office of Engineering and Technology  
445 12TH ST SW  
Washington DC 20554

RE: - FCC ID: SWX-M5P

To Whom It May Concern:

During a recent review of the information provided during the original application submission of FCC ID: SWX-M5P, it was brought to our attention that some testing was inadvertently performed incorrectly. The test lab has taken the initiative to correct this error by retesting the sample and updated the report and grant for certification.

No products were sold with the previously reported power settings.

Sincerely,

A handwritten signature in black ink, appearing to read "Robert J. Pera", is written over a light yellow rectangular background.

Robert Pera  
CEO/Founder  
Ubiquiti Networks