Michael Royer, 11:12 AM 3/2/2005 -0600, RE: Review of DLP Design, Inc., FCC ID: SX9000RF2 after... Page 1 of 1 Timothy,

The averaging in this report was not revisited. The data was re-collected with the shields attached, nothing more. We will update the label exhibit.

Best regards, Mike

Michael Royer BSEE