

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

Gentlemen:

We confirm that following modification was made to FCC ID: SY55WY8412 model for upgrading the set :

5WY8412 Model's Modification List

1. The value of L1 is changed from "270 nH" to "220 nH" to enhance spurious.
2. The firmware is upgraded to enhance transmission timing.

Sincerely yours,



Shi-Hong Sung
/Manager
/Siemens Automotive

If you have not received all pages, please call the direct phone number.
FAX : 031-630-0891 TEL : 031-630-0820