

Tyco/Software House
70 Westview St.
Lexington, MA 20421
May 08, 2006

RE: Model Number Comparisons

To whom it may concern:

This letter is to inform you of the model differences between our RM-PI37, RM1-PI37, and RM2L-PI37 card readers. In addition to the documentation supplied detailing that the schematic and read head are identical, Tyco/Software House would like to emphasize that there are no deviations in the software or hardware assemblies other than the following denotations:

- RM-PI37 = 37 bit Indala read head, 0311-0163-01 without keypad or LCD display.
- RM1-PI37 = 37 bit Indala read head, 0311-0163-01 with keypad only.
- RM2L-PI37 = 37 bit Indala read head, 0311-0163-01 with keypad and LCD display.

Whether the keypad or LCD is or is not provided, there is no difference in the software or assembly of the printed circuit board. The schematic and printed circuit board components remain identical for each model number described. The RM2L-PI37 was presented as the test sample due to the additional keypad and LCD options. The host computer was operating the CCURE 800 v9.0 software as the means for verifying operation during the test.

If you have any question please call me at 781-768-0205 or by email at joloiselle@tycoint.com

Regards,

John Loïselle

John Loïselle
Regulatory Engineer
Tyco/Software House
joloiselle@tycoint.com
Phone: (781) 768-0205
Fax: (781) 768-0103