

Tyco/Software House  
70 Westview St.  
Lexington, MA 20421  
June 29, 2006

RE: Changes to previously granted models:

FCC ID: SZC-RMXIC  
IC ID: 5690A-RMXIC

To whom it may concern:

This letter is to inform you of the changes made to our RM-IC, RM1-IC, and RM2L-IC card readers. In addition to the documentation supplied detailing that the read head is unchanged, we are providing an updated schematic for the :

- RM-IC = HID OEM050 read head, 0311-0163-07 without keypad or LCD display.
- RM1-IC = HID OEM050 read head, 0311-0163-07 with keypad only.
- RM2L-IC = HID OEM050 read head, 0311-0163-07 with keypad and LCD display.

Whether the keypad or LCD is or is not provided, there is no difference in the software or assembly of the printed circuit board. The schematic and printed circuit board components for each model number described are very similar to the information on file. The changes that were made include improved EMI filtering and transient protection circuitry, RoHS Directive compliant components, and the use of a lead free manufacturing process. The part number for the printed circuit board has been changed to denote these differences. The RM2L-IC was presented as the test sample due to the additional keypad and LCD options. The host computer was operating the CCURE 800 v9.0 software as the means for verifying operation during the test.

If you have any question please call me at 781-768-0205 or by email at [joloiselle@tycoint.com](mailto:joloiselle@tycoint.com)

Regards,

John Loiselle

John Loiselle  
Regulatory Engineer  
Tyco/Software House  
[joloiselle@tycoint.com](mailto:joloiselle@tycoint.com)  
Phone: (781) 768-0205  
Fax: (781) 768-0103