

YEALINK(XIAMEN) NETWORK TECHNOLOGY CO.,LTD.

309, 3rd Floor, No.16, Yun Ding North Road, Huli District, Xiamen City, Fujian, China

Tel: 86-592-5702000

Fax: 86-592-5702455

Email: chenjl@yealink.com

Date: 2021-07-31

FEDERAL COMMUNICATIONS COMMISSIONS

Authorization and Evaluation Division

7435 Oakland Mills Road


Columbia, MD 21046

To whom it may concern:

The RF chip, model EFR32BG22C224F512GM40-C, which installed in our product Room Sensor, Model: RoomSensor, FCC ID: T2C-SENSOR503, supports BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK), BLE 1M and BLE 2M functions. For use in America and this chip will not support/enable BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK) and BLE 2M. The BDR (GFSK), EDR ($\pi/4$ -DQPSK, 8DPSK) and BLE 2M function has been shielded by the manufacturer using the software.

Sincerely,

Signature:



Stone Lu

Vice General Manager