





<u>INTERNAL PHOTOS</u>	
Company Name	Scott Safety, Division of Scott Technologies, Inc
Model #	201211
FCC ID #	T5E-201211
IC #	6453A-201211




<u>INTERNAL PHOTOS</u>	
Company Name	Scott Safety, Division of Scott Technologies, Inc
Model #	201211
FCC ID #	T5E-201211
IC #	6453A-201211



INTERNAL PHOTOS	
Company Name	Scott Safety, Division of Scott Technologies, Inc
Model #	201211
FCC ID #	T5E-201211
IC #	6453A-201211




Front of board with RFID section




Close up of front side RFID section

INTERNAL PHOTOS	
Company Name	Scott Safety, Division of Scott Technologies, Inc
Model #	201211
FCC ID #	T5E-201211
IC #	6453A-201211




Back of board with RFID section




Close up of back side RFID section

INTERNAL PHOTOS	
Company Name	Scott Safety, Division of Scott Technologies, Inc
Model #	201211
FCC ID #	T5E-201211
IC #	6453A-201211




Front side of board with Apex LT Module



Close up of Apex LT module with shield removed

<u>INTERNAL PHOTOS</u>	
Company Name	Scott Safety, Division of Scott Technologies, Inc
Model #	201211
FCC ID #	T5E-201211
IC #	6453A-201211



Back side of board with Apex LT module