

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request for change of identification per section 2.933 of FCC rules

Date: 2018-11-28

Reference: **FCC ID: T8H-SEICLASS (new FCC ID)**

To The Commission:

This Change of Identification request applies for a new **FCC ID: T8H-SEICLASS** as established in 47CFR 2.933(b) for a currently approved device. This application by dormakaba USA Inc. will establish a new FCC ID under **(T8H) grantee code** corresponding to **FRN: 0006806095** for the purpose of marketing. The original grant to **FCC ID: JQ6-SE3210 (original ID)** will remain in effect.

An authorization letter by HID Global Corporation is attached.

Per 2.933(b)

1. The original identification is FCC ID: JQ6-SE3210
2. The grant date is 02/07/2013
3. The equipment is electrically identical. Only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

Cover Letter

External Photos

FCC ID label format and location

User's manual

Sincerely,



E.J. Caylor / RF Engineer

Tel: 317-806-3501

Email: [ej.caylor@dormakaba.com](mailto:ej.caylor@dormakaba.com)

BEST Access Solutions, Inc.  
6161 E. 75<sup>th</sup> Street  
Indianapolis, IN 46250  
t 855.365.2407  
f 877.835.1030



STANLEY