ERICSSON 📕		Open		
		EXHIBIT 7		
	No.			
Checked	Date	Rev	Reference	
	10/20/2006	А	TA8AKRC161134-4	
	Checked	EXHIBIT 7 No. Checked Date	EXHIBIT 7 No. Checked Date Rev	EXHIBIT 7 No. Checked Date Rev Reference

Federal Communications Commission Authorization & Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046 Attention: Equipment Authorization Branch

1 Tune-Up Procedure

All the necessary adjustments will be set in the factory, and no adjustments are needed. The Base Station Controller (BSC) remotely controls the maximum output power level of the Base Station (BS). If the Radio Equipment is not able to maintain the requirements for power output, frequency stability, etc an alarm is sent to the BSC and the fault is corrected or the Radio Unit is disabled.

If additional information is needed, please contact me on the below listed number.

Regards,

Keith A. Goshia Engineer Staff Manager Ericsson Wireless 6210 Spine Road Boulder, CO 80301 Telephone: (303) 473-6956 Fax: (303) 473-6646 e-mail: keith.goshia@ericsson.com