Ericsson Internal

## ERICSSON 🗾

Prepared (also subject responsible if other)		No.		
ETCCHWQ		287AB-AS161566		
Approved	Checked	Date	Rev	Reference
CBC/XRV/D Weiqn Chen		2016-02-03	A	

Industry Canada Certification and Engineering Bureau 3701 Carling Avenue, Bldg.94 P.O. Box 11490, Station "H" Ottawa, Ontario K2H 8S2 Canada TUV SUD BABT FCB Octagon House, Concorde Way Fareham, Hampshire, PO15 5RL United Kingdom 1(1)

## **Attestation Letter of Family Products Relationship**

We, Ericsson AB, hereby apply Family Certification. The HVIN, AS1615661 and AS1615662 are 850MHz Radio Unit. The differences between them is AS1615661 without TX monitor port, AS1615662 has two TX monitor ports.

If additional information is needed, please contact me on the below listed number.

飞来的最多

Weiqun Chen Staff Engineer, Regulatory Programs Ericsson AB Isafjordsgatan 10 Kista, SE-164 80 Stockholm Sweden Telephone No.: +86 10 84767227 e-mail: weigun.chen@ericsson.com