



Exhibit 03: External Photographs – Ericsson Confidential

KRC 161 983/31: Photo Submission (External)
Radio 4890HP 48B2/B25 48B66 M01 (Multi-Standard)

FCC ID: TA8AKRC161983-3
IC: 287AB-AS1619833
HVIN: AS1619833

Date: 09 June 2023
Author: Ericsson Canada
File: Radio 4890HP External Photos



CONFIDENTIAL INFORMATION
RESTRICTED USE AND DUPLICATION
© Ericsson Canada Inc. All Rights Reserved.

The information contained in this document is the property of Ericsson Canada. Except as specifically authorized in writing by Ericsson, the holder of this document shall keep all information contained herein confidential and shall protect same in whole or in part from disclosure and dissemination to all third parties.




Figure 1: Radio 4890HP 48B2/B25 48B66 M01 Bottom / Connector View



Figure 2: Radio 4890HP 48B2/B25 48B66 M01 Top / Handle View




Figure 3: Radio 4890HP 48B2/B25 48B66 M01 Front / Back (Mounting) View



Figure 4: Radio 4890HP 48B2/B25 48B66 M01 Side View

	Radio 4890HP 48B2/B25 48B66 M01	B2/B25 UL 1850-1915 MHz DL 1930-1995 MHz
		B66 UL 1710-1780 MHz DL 2110-2200 MHz
	ETL LISTED INFORMATION TECHNOLOGY EQUIPMENT Control number 113813	FCC ID: TA8AKRC161983-3 IC: 287AB-AS1619833 AS1619833
		This device complies with Part 15 of the FCC rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device accepts any interference received, including interference that may cause undesired operation. CAN ICES-3 (B)/NMB-3 (B).
		Ericsson AB, 164 80 Stockholm, Sweden
IP65 / Type 3 Enclosure		

Figure 5: Radio 4890HP 48B2/B25 48B66 M01 Product Labels