

Change in Identification

PHOENIX TESTLAB GmbH
Product Certification
Königswinkel 10

Date: December 17, 2009

D 32825 Blomberg

Class II Permissive Change
FCC ID TBURFIDLF
IC: 5736-RFIDLF

Dear Sir or Madam,

The reason of change is because of marketing.
A RFID reader was attached. The reader is deactivated in charging mode.

Thank you for your attention in this matter.

Applicant's Company : TÜV SÜD SENTON GmbH
address : Auessere Fruehlingstrasse 45, D-94315 Straubing

Signature

: 
Johann Roidt

Job Title and Dept. : Technical Director