



June 2, 2008

To whom it may concern,

Bluetooth fitted but permanently disabled

This letter serves to confirm that an OEM Bluetooth module is fitted to our product, FCC ID TFTIDL3ID01, but permanently disabled and not available to the user of the product. The following comprehensive steps have been taken to achieve this:

1. Removing the Bluetooth drivers from the product Operating System. This ensures that an application cannot interface to the module.
2. Removing Bluetooth power up and power management from the Operating System. This ensures that power is not supplied to the module.
3. Removing the Bluetooth selection from the Wireless Manager application. This ensures that a user is not able to manually enable Bluetooth.

Sincerely,

A handwritten signature in black ink, appearing to read "Roger Biggs".

Roger Biggs
Technical Director