




Internal view 1 (bottom cover removed)

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 1 of 9






Internal view 2 (housing removed)

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 2 of 9






Internal view 3 (view to PCBs)

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 3 of 9





DoserDetectionRFID PCB, top view

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 4 of 9





DoserDetectionRFID PCB, bottom view

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 5 of 9






MotorControlFOC PCB, top view

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 6 of 9






MotorControlFOC PCB, bottom view

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 7 of 9






DoserControl PCB, top view

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 8 of 9





DoserControl PCB, bottom view

 Examiner: Thomas KÜHN
 Revision:
 00

 Date of issue: 21.04.2021
 Order Number:
 21-1105625
 page 9 of 9