

---

**Subject:** FW: Pan Communications, Inc., FCC ID: TI4-UCS-301, Assessment NO.: AN05T5080, Notice#1



Exhibit A1  
Authorizatin Letter..



Exhibit L Test  
Report.pdf

Dear Ms. Helen

My reply is as follws,

Regarding to Q1: I amended the test report. please see the attached.

Regarding to Q2: The FCC ID is TI4-UCA-301, the No. TI4-UCS-301 was miss.

Regarding to Q3: Please see the attached.

If you have other question, please contact to me.

Sincerely yours,  
Masanori Takahashi

-----Original Message-----

From: Compliance Certification Services [mailto:helen.zhao@ccsemc.com]  
Sent: Monday, August 22, 2005 4:41 PM  
Subject: Pan Communications, Inc., FCC ID: TI4-UCS-301, Assessment NO.: AN05T5080, Notice#1

Question #1: The test setup diagram on page 10 of the test report is not displayed properly. Please resubmit the revised test report.

Question #2: Please verify FCC ID. The ID listed on Form 731 (TI4-UCS-301) is different from the ID listed in the documents in the filing (TI4-UCA-301).

Question #3: Please submit an Agency Authorization Letter.

Best Regards,  
Helen Zhao

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.