

CONFIDENTIAL

Panther Installation Guide

ESI Proprietary and Confidential

CONFIDENTIAL

REGULATORY INFORMATION	3
INTRODUCTION	4
ABOUT THE PANTHER READER	4
<i>Basic Features</i>	4
<i>Advanced Features</i>	4
LICENSING	4
SYSTEM REQUIREMENTS	5
<i>Capacities</i>	5
SPECIFICATIONS	5
ABOUT DOOR LOCK CONTROL	6
ELECTRIC AND ELECTROMAGNETIC DOOR LOCKS	6
DISCLAIMER	7
FEATURE SUMMARY	8
BASIC FEATURES	8
RFID FEATURES	8
INSTALLING THE RFID READER	9
MOUNTING AND CONNECTING	9
PROGRAMMING	11
OVERVIEW	11
PROGRAMMING FUNCTIONS	11
<i>Function 157: Door unlock timer</i>	11
<i>Function 169: System Features</i>	12
<i>Function 37 - RFID programming</i>	12
<i>Function 371 - Access Schedule programming</i>	12
<i>Function 372 - RFID Tag programming</i>	14
<i>User programming</i>	15
HOW TO PROGRAM	15
<i>Overview</i>	15
<i>Non-RFID features</i>	15
<i>RFID applications</i>	15
HOW TO PROGRAM FOR SPECIFIC APPLICATIONS	15
RFID READER DISPLAY REFERENCE	16
TROUBLESHOOTING	16
GLOSSARY	16

CONFIDENTIAL

Regulatory information

United States of America

FCC Part 15

FCC Notice: Any change or modification not expressly approved by the manufacturer could void the user's authority to operate the equipment.

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions (1) This device may not cause harmful interference, and (2) This device must accept any interference that may cause undesired operation.

This equipment has been tested and found to comply with the limits for a class B digital device, pursuant to part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses, and can radiate radio frequency energy and if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- *Reorient or relocate the receiving antenna*
- *Increase the separation between the equipment and receiver*
- *Consult the dealer or an experienced radio/TV technician for help*

FCC Registration

FCC TX ID: 1T1PR0345