
Test setup photographs of module.





ROGERS LABS, INC. Hopkins Manufacturing Corp. FCC ID: TJJ-BB002 4405 West 259<sup>th</sup> Terrace MODEL: Brake Buddy Vantage IC:6047A-BB002 Louisburg, KS 66053 Test #:051007

Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.247, RSS-210 Page 1 of 3 BB002 Test setup photos.Doc 12/8/2005

Test setup photographs of transmitter located in applications.





ROGERS LABS, INC. Hopkins Manufacturing Corp.
4405 West 259<sup>th</sup> Terrace MODEL: Brake Buddy Vantage
Louisburg, KS 66053 Test #:051007

Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.247, RSS-210 Page 2 of 3

FCC ID: TJJ-BB002 IC:6047A-BB002

Transmitter located inside host unit was also tested and found to comply.





ROGERS LABS, INC. Hopkins Manufacturing Corp. FCC ID: TJJ-BB002 4405 West 259<sup>th</sup> Terrace MODEL: Brake Buddy Vantage IC:6047A-BB002 Louisburg, KS 66053 Test #:051007

Phone/Fax: (913) 837-3214 Test to: FCC Parts 2 and 15.247, RSS-210 Page 3 of 3 BB002 Test setup photos.Doc 12/8/2005