From:Claire HoqueSent:Thursday, September 08, 2005 11:49 AMTo:Helen ZhaoCc:William Lau; Thu Chan; Christine VuSubject:answer: MobileAria, Inc. , FCC ID: TJZVTCUEV, Assessment NO.: AN05T5105, Notice#1
(revised)









VTCU Theory of VTCU_install_guide FCC 05U3604-1B FCC Operation(revis... _21b(revised... Label(revised).pdf DTS Report(Rev...

... Hi Helen,

Here are the answers.

Question #1: Theory of Operation indicates "The VTCU is manufactured using a Sierra Wireless EM5625D (EVDO)", but only DTS portion is filed this time. Please advise whether the EVDO module has been certified. If so, please clearly indicate FCC ID in the filing, otherwise you may need to submit a separate filing to address licensed device requirement. <answer>page 6 of report is revised to include Sierra Wireless EM5625D module FCC ID.

Question #2: Theory of Operation clearly indicates "The VTCU contains an internal 802.11b or g module", this filing covers 802.11b only. Please advise whether the device has capability to operate at 802.11g mode. If so, you may need to provide test data with 802.11g module. <a href="mailto:sawerstright the operate at 802.11g module.

Question #3: This device uses a Sierra Wireless modem, if the module has got modular approval, please modify FCC ID label format to include "Contains FCC ID: <Sierra Wireless module ID>". This device is a PC peripheral, please verify the digital portion is authorized by DoC or certification, if it is DoC, please add DoC logo on label format, otherwise, please submit a separate for digital portion certification. <answer>FCC label is revised to include FCC DoC logo.

Question #4: The test report section 5.1 is misleading. Since there are two radio modules, please indicate clearly the manufacturer of each module, if Sierra Wireless module has been certified, please indicate FCC ID as well.

<answer>Please see revised report under section 5.1 on page 6.

Question #5: The test data listed on page 50 of the test report is not clear enough, please resubmit test data. <answer>Please see revised report on page 50.

Question #6: The user manual does not contain RF exposure statement as specified in FCC15.247(i). Please update user manual. <answer>User Manual is revised as attached.

Thanks,

Claire