

Appendix A. Test Photos

Radiated Emissions below 1GHz



Radiated Emissions below 1GHz



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 60 of 63 Report Version : 01


FCC ID TLZ-WH036

Report No.: FR0N1918




Report No.: FR0N1918

Radiated Emissions above 1 GHz



Radiated Emissions above 1 GHz



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 61 of 63

Report Version : 01

FCC ID TLZ-WH036



eport Report No. : FR0N1918

AC Power Conducted



AC Power Conducted



SPORTON INTERNATIONAL INC.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : 62 of 63 Report Version : 01

FCC ID TLZ-WH036

Appendix B. Photographs of EUT

Please refer to Sporton report number **EP0N1918** as below.

Report No.: FR0N1918

SPORTON INTERNATIONAL INC. Page No. : 63 of 63
TEL: 886-2-2696-2468 Report Version : 01

FAX: 886-2-2696-2255 FCC ID TLZ-WH036