

March 12, 2009

SUBJECT: TIMCO-TCB/Request for additional info - MAGNETEK -

FCC ID: TNE-430PEN2

REFERENCE: JOB 327UC9

Based upon our review of this application we have the following issues:

1. **Block Diagram:** please explain why this document does not comply with 47 CFR Part 2 Section 2.1033(b)(5). All oscillators their frequencies and signals paths must be shown. Alternatively, include the required information and resubmit the document.

A new block diagram showing all frequencies has been uploaded to TIMCO.

2. **User Manual:** please explain why this document does not contain the information required by 47 CFR Part 15 Subsection A section 15.21. Alternatively, include the required information and resubmit the document.

A new User's Manual containing the required 47 CFR Part 15 information has been uploaded.

3/5/2009 – Added below item

3. **CONFIDENTIALITY REQUEST LETTER:** The FCC has requested that the request for confidentiality letter justify the request for the Users Manual to be under long-term confidentiality

A new Confidentiality Request Letter has been uploaded justifying the confidentiality request of the users manual.

Regards,
Colleen Reitz
Publications Department
215.256.4133 ext. 350
RETLIF Testing Laboratories
www.retlif.com