



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:16:48

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:16:58

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:17:11

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:17:21

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:17:34

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:17:44

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:18:48

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:18:58

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:19:11

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:19:21

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:19:34

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:19:44

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:20:25

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:20:36

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:20:48

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:20:59

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:21:12

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:21:22

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:22:08

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:22:18

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:22:35

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:22:45

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:23:01

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:23:11

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:24:10

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:24:20

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:24:34

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:24:44

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:24:58

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:25:08

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:26:07

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:26:17

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:26:34

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:26:44

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:26:58

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:27:08

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:27:29

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:27:39

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:27:55

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:28:05

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:28:18

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:28:28

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:29:22

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:29:33

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:29:49

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:29:59

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:30:12

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:30:22

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:30:59

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:31:09

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:31:22

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:31:33

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:31:49

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:31:59

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:32:47

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:32:57

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:33:10

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:33:20

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:33:33

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:33:44

Band 4_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:34:50

Band 4_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:35:00

Band 4_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:35:14

Band 4_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:35:24

Band 4_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:35:38

Band 4_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:35:48

Band 4_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:36:32

Band 4_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:36:42

Band 4_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:37:00

Band 4_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:37:10

Band 4_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:37:27

Band 4_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 11.OCT.2022 11:37:37

Band 7_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:37:55

Band 7_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:38:05

Band 7_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:38:18

Band 7_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:38:31

Band 7_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:38:44

Band 7_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:38:55

Band 7_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:39:43

Band 7_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:39:53

Band 7_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:40:06

Band 7_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:40:16

Band 7_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:40:33

Band 7_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:40:43

Band 7_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:42:50

Band 7_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:43:01

Band 7_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:43:14

Band 7_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:43:25

Band 7_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:43:41

Band 7_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:43:52

Band 7_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:44:49

Band 7_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:44:59

Band 7_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:45:13

Band 7_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:45:23

Band 7_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 11:45:40

Band 7_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 11:45:51

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:47:30

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:47:41

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:47:53

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:48:04

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:48:16

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:48:27

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:53:23

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:53:33

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:53:46

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:53:56

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:54:12

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:54:22

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:55:06

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:55:17

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:55:33

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:55:43

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:55:56

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:56:06

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:56:54

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:57:04

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:57:17

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:57:28

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:57:41

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:57:51

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:58:09

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:58:19

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:58:32

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:58:42

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:58:58

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:59:08

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 13:59:49

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 11.OCT.2022 13:59:59

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:00:12

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:00:22

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:00:35

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:00:45

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:01:23

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:01:33

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:01:46

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:01:57

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:02:09

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:02:20

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:05:54

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:06:04

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:06:21

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:06:31

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:06:44

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:06:54

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:07:12

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:07:22

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:07:38

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:07:48

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:08:01

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:08:11

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:08:49

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:08:59

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:09:12

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:09:22

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:09:36

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 11.OCT.2022 14:09:46

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:56:53

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 14:57:03

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:57:16

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 14:57:26

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:57:42

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 14:57:52

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:58:34

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 14:58:44

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:59:00

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 14:59:11

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 14:59:24

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 14:59:34

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 15:00:24

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 15:00:34

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 15:00:48

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 15:00:58

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 15:01:12

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 15:01:22

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 15:02:01

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 15:02:11

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 15:02:25

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 15:02:35

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 15:02:52

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 15:03:02

LTE Band 40 (2305~2315MHz) CSE 5MHz-Low CH-QPSK-1




Date: 8.NOV.2022 15:16:16

LTE Band 40 (2305~2315MHz) CSE 5MHz-Low CH-QPSK-2




Date: 8.NOV.2022 15:16:53

LTE Band 40 (2305~2315MHz) CSE 5MHz-Low CH-QPSK-3




Date: 8.NOV.2022 15:17:33

LTE Band 40 (2305~2315MHz) CSE 5MHz-Middle CH-QPSK-1




Date: 8.NOV.2022 15:19:41

LTE Band 40 (2305~2315MHz) CSE 5MHz-Middle CH-QPSK-2




Date: 8.NOV.2022 15:20:20

LTE Band 40 (2305~2315MHz) CSE 5MHz-Middle CH-QPSK-3




Date: 8.NOV.2022 15:20:59

LTE Band 40 (2305~2315MHz) CSE 5MHz-High CH-QPSK-1




Date: 8.NOV.2022 15:21:50

LTE Band 40 (2305~2315MHz) CSE 5MHz-High CH-QPSK-2




Date: 8.NOV.2022 15:22:22

LTE Band 40 (2305~2315MHz) CSE 5MHz-High CH-QPSK-3




Date: 8.NOV.2022 15:22:58

LTE Band 40 (2305~2315MHz) CSE 10MHz-Middle CH-QPSK-1




Date: 8.NOV.2022 15:24:08

LTE Band 40 (2305~2315MHz) CSE 10MHz-Middle CH-QPSK-2




Date: 8.NOV.2022 15:24:47

LTE Band 40 (2305~2315MHz) CSE 10MHz-Middle CH-QPSK-3




Date: 8.NOV.2022 15:25:25

LTE Band 40 (2350~2360MHz) CSE 5MHz-Low CH-QPSK-1




Date: 8.NOV.2022 15:26:54

LTE Band 40 (2350~2360MHz) CSE 5MHz-Low CH-QPSK-2




Date: 8.NOV.2022 15:27:34

LTE Band 40 (2350~2360MHz) CSE 5MHz-Low CH-QPSK-3




Date: 8.NOV.2022 15:28:13

LTE Band 40 (2350~2360MHz) CSE 5MHz-Middle CH-QPSK-1




Date: 8.NOV.2022 15:29:16

LTE Band 40 (2350~2360MHz) CSE 5MHz-Middle CH-QPSK-2




Date: 8.NOV.2022 15:29:56

LTE Band 40 (2350~2360MHz) CSE 5MHz-Middle CH-QPSK-3




Date: 8.NOV.2022 15:30:35

LTE Band 40 (2350~2360MHz) CSE 5MHz-High CH-QPSK-1




Date: 8.NOV.2022 15:31:33

LTE Band 40 (2350~2360MHz) CSE 5MHz-High CH-QPSK-2




Date: 8.NOV.2022 15:32:13

LTE Band 40 (2350~2360MHz) CSE 5MHz-High CH-QPSK-3




Date: 8.NOV.2022 15:32:51

LTE Band 40 (2350~2360MHz) CSE 10MHz-Middle CH-QPSK-1




Date: 8.NOV.2022 15:33:32

LTE Band 40 (2350~2360MHz) CSE 10MHz-Middle CH-QPSK-2




Date: 8.NOV.2022 15:36:58

LTE Band 40 (2350~2360MHz) CSE 10MHz-Middle CH-QPSK-3




Date: 8.NOV.2022 15:34:49

Band 41_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:23:47

Band 41_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:23:57

Band 41_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:24:13

Band 41_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:24:23

Band 41_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:24:36

Band 41_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:24:46

Band 41_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:25:02

Band 41_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:25:12

Band 41_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:25:26

Band 41_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:25:36

Band 41_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:25:49

Band 41_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:25:59

Band 41_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:26:18

Band 41_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:26:29

Band 41_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:26:42

Band 41_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:26:52

Band 41_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:27:06

Band 41_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:27:16

Band 41_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:27:33

Band 41_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:27:43

Band 41_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 11.OCT.2022 16:27:57

Band 41_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 11.OCT.2022 16:28:07

Band 41_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 11.OCT.2022 16:28:21

Band 41_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 11.OCT.2022 16:28:31