




**UNII-2C / 802.11a / Low ch.**



**UNII-3 / 802.11a / Low ch.**




**UNII-2C / 802.11a / Mid ch.**




**UNII-3 / 802.11a / Mid ch.**




**UNII-2C / 802.11a / High ch.**




**UNII-3 / 802.11a / High ch.**




**UNII-1 / 802.11n HT20 / Low ch.**



**UNII-2A / 802.11n HT20 / Low ch.**




**UNII-1 / 802.11n HT20 / Mid ch.**




**UNII-2A / 802.11n HT20 / Mid ch.**




**UNII-1 / 802.11n HT20 / High ch.**



**UNII-2A / 802.11n HT20 / High ch.**




**UNII-2C / 802.11n HT20 / Low ch.**




**UNII-3 / 802.11n HT20 / Low ch.**




**UNII-2C / 802.11n HT20 / Mid ch.**




**UNII-3 / 802.11n HT20 / Mid ch.**



**UNII-2C / 802.11n HT20 / High ch.**



**UNII-3 / 802.11n HT20 / High ch.**



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0051


Page (39) of (205)




## UNII-1 / 802.11n HT40 / Low ch.




## UNII-2A / 802.11n HT40 / Low ch.



## UNII-1 / 802.11n HT40 / High ch.



## UNII-2A / 802.11n HT40 / High ch.



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0051


Page (40) of (205)




## UNII-2C / 802.11n HT40 / Low ch.



## UNII-3 / 802.11n HT40 / Low ch.




## UNII-2C / 802.11n HT40 / Mid ch.



## UNII-3 / 802.11n HT40 / High ch.




## UNII-2C / 802.11n HT40 / High ch.




Blank


**UNII-1 / 802.11ac VHT20 / Low ch.**



**UNII-2A / 802.11ac VHT20 / Low ch.**




**UNII-1 / 802.11ac VHT20 / Mid ch.**




**UNII-2A / 802.11ac VHT20 / Mid ch.**




**UNII-1 / 802.11ac VHT20 / High ch.**




**UNII-2A / 802.11ac VHT20 / High ch.**




**UNII-2C / 802.11ac VHT20 / Low ch.**




**UNII-3 / 802.11ac VHT20 / Low ch.**




**UNII-2C / 802.11ac VHT20 / Mid ch.**




**UNII-3 / 802.11ac VHT20 / Mid ch.**



**UNII-2C / 802.11ac VHT20 / High ch.**



**UNII-3 / 802.11ac VHT20 / High ch.**



# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0051


Page (43) of (205)




## UNII-1 / 802.11ac VHT40 / Low ch.




## UNII-2A / 802.11ac VHT40 / Low ch.



## UNII-1 / 802.11ac VHT40 / High ch.



## UNII-2A / 802.11ac VHT40 / High ch.





# KCTL Inc.


65, Sinwon-ro, Yeongtong-gu,  
Suwon-si, Gyeonggi-do, 16677, Korea  
TEL: 82-31-285-0894 FAX: 82-505-299-8311  
[www.kctl.co.kr](http://www.kctl.co.kr)

Report No.:  
KR20-SRF0051


Page (44) of (205)




## UNII-2C / 802.11ac VHT40 / Low ch.




## UNII-3 / 802.11ac VHT40 / Low ch.




## UNII-2C / 802.11ac VHT40 / Mid ch.



## UNII-3 / 802.11ac VHT40 / High ch.



## UNII-2C / 802.11ac VHT40 / High ch.



Blank