ATC40S8AN, ATC40S8KN

FCC/IC LABEL Information

	YZP-VL3000
IC:	5074A-ATC40S8KN
IC MODEL:	ATC40S8KN
Contains IC:	7414C-BK1100
Operation is subject to (1) This device may no (2) This device must ac	vith part 15 of the FCC rules the following two conditions: t cause harmful interference, and ccept any interference received, that may cause undesired

MANUFACTURED BY HYUNDAI MOBIS

PRODUCT LABEL

LABEL LOCATION



FRONT TOP

ATC41S8AN, ATC41S8KN

FCC/IC LABEL Information

Hyundai MOBIS Co., Ltd.		LABEL LOCATION			
FCC ID:	TQ8-ATC40S8AN D: YZP-VL3000 5074A-ATC40S8KN ATC41S8KN 7414C-BK1100				
This device complies with part 15 of the FCC rules Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.				Non-removable LABEL	
MANUFACTURED BY HYUNDAI MOBIS					
PRODUCT	Γ LABEL				J
				FRONT TOP	