Cover Letter

FCC ID:	TTUCR870-2Q
Date:	March 08, 2012

Comments	Quietek Lab.	
1. Please provide MPE analysis. Note that the sample	Please see the revised RF Exposure report	
analysis sent in via e-mail contains an error - the		
numbers in the 4th column of the tables on Page 3		
are not distances as indicated in the footnote for the		
1 mW/cm^2 limit but instead the power density at 20		
cm.		
2. Page 29 of the OEM/ODM User's Manual contains	Please see the revised manual.	
antenna listing for compliance to Industry Canada	Antenna listing information for FCC sections is	
regulation. Similar information is needed in the FCC	added on page 28/29.	
sections. The FCC test report on Page 5 does contain		
such list. To avoid confusion, the grantee should		
revise the user's manual. Furthermore, the module's		
antenna connector is a standard UFL connector,		
hence it is important to let OEM/ODM who plans to		
build products for the US market knows the limitation		
on antenna selection.		
3. The grantee is currently using the manufactuer	Please see POA letter.	
user's manual which is a BridgeCo confidential and		
copyrighted document (see Page 26 copyright		
statements). The grantee should present its own		
user's manual or obtain authorization, including		
scope of authorization, from the copyright holder.		