

Tune-up Procedure

Each unit is tested during unit production for performance and functionality against pass/fail criteria. The unit is then given pass/fail status based on measured functionality parameters. The pass/fail threshold is determined by engineering during product development. Compliant samples continue through production and non-compliant units are removed.