


Internal photographs of equipment under test (inside enclosure)  
Shield removed for photograph



Back side of EUT PCB




Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Mikrotiks SIA  
Model: RB2011US-2HnD-IN  
Test #: 120416  
Test to: CFR47 (15.247)  
File: IntPho RB20112HnD

SN: 35A901DD0B69  
FCC ID#: TV7RB2011-2HND  
Date: May 25, 2012  
Page 1 of 2

Top side of PCB shields in place



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Mikrotikls SIA  
Model: RB2011US-2HnD-IN  
Test #: 120416  
Test to: CFR47 (15.247)  
File: IntPho RB20112HnD

SN: 35A901DD0B69  
FCC ID#: TV7RB2011-2HND  
Date: May 25, 2012  
Page 2 of 2