



Internal photographs of equipment under test  
Shield removed for photograph



Shield in place




Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Mikrotiks SIA  
Model: RB922UAGS-5HPacT-US  
Test #: 170310  
Test to: CFR47 (15.247)  
File: RB9225HPACTM IntPho

S/N: 6060059FADA3  
IC: 7442A-9225HPACTM  
FCC ID: TV7RB922-5HPACTM  
Date: July 17, 2017  
Page 1 of 2

Back side



Rogers Labs, Inc.  
4405 W. 259th Terrace  
Louisburg, KS 66053  
Phone/Fax: (913) 837-3214  
Revision 1

Mikrotiks SIA  
Model: RB922UAGS-5HPacT-US  
Test #: 170310  
Test to: CFR47 (15.247)  
File: RB9225HPACTM IntPho

S/N: 6060059FADA3  
IC: 7442A-9225HPACT  
FCC ID: TV7RB922-5HPACTM  
Date: July 17, 2017  
Page 2 of 2