





External photographs of equipment under test



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Mikrotiks SIA
Model: RB953GS-5HnT-RP-US
Test #: 170316
Test to: 47CFR, 15.407, RSS-247
File: RB953GS-5HnT-RP-US FCC ExtPho Page 1 of 4



S/N: 54EE04337EEF
FCC ID: TV7RB953GS5HNTM
IC: 7442A-RB953GS5HNT
Date: April 3, 2017



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Mikrotiks SIA
Model: RB953GS-5HnT-RP-US
Test #: 170316
Test to: 47CFR, 15.407, RSS-247
File: RB953GS-5HnT-RP-US FCC ExtPho

S/N: 54EE04337EEF
FCC ID: TV7RB953GS5HNTM
IC: 7442A-RB953GS5HNT
Date: April 3, 2017
Page 2 of 4



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Mikrotiks SIA
Model: RB953GS-5HnT-RP-US
Test #: 170316
Test to: 47CFR, 15.407, RSS-247
File: RB953GS-5HnT-RP-US FCC ExtPho

S/N: 54EE04337EEF
FCC ID: TV7RB953GS5HNTM
IC: 7442A-RB953GS5HNT
Date: April 3, 2017
Page 3 of 4



Rogers Labs, Inc.
4405 W. 259th Terrace
Louisburg, KS 66053
Phone/Fax: (913) 837-3214
Revision 1

Mikrotiks SIA
Model: RB953GS-5HnT-RP-US
Test #: 170316
Test to: 47CFR, 15.407, RSS-247
File: RB953GS-5HnT-RP-US FCC ExtPho Page 4 of 4

S/N: 54EE04337EEF
FCC ID: TV7RB953GS5HNTM
IC: 7442A-RB953GS5HNT
Date: April 3, 2017