



Bureau Veritas Consumer Products Services (H.K.) Ltd., Taoyuan Branch
No. 19, Huaya 2nd Rd., Guishan Dist., Taoyuan City 33383, Taiwan (R.O.C.).

Dear Commission,

Re: Test Report Supersede Request

FCC ID: TVE-4617T06785

2020/10/27

Due to the reason specified below, we have mistakenly included extra data in the submitted NII Test Report which the Grantee, Fortinet Inc., would like us to remove within the test report exhibit on FCC EAS database to avoid confusion. We apologize for the error and please help us to supersede the incorrect test report. Thank you and we appreciate your help.

Problem brief:

HT20 and HT40 Beamforming modes were supported in the initial product specifications, so we tested all RF parameters to find the worst mode for inclusion in the report. However, during the report compilation process, the client decided to disable support of HT20 and HT40 Beamforming modes in the final version. We failed to remove this data in the final submitted test report and that is why HT20 and HT40 Beamforming power data can still be seen.

Best regards,

Bruce Chen / Senior Project Engineer