

**1.5. EUT Exercise Software**

Test Mode	Mode 1: Slide Show
1	Setup EUT and PC as shown on 1.4.
2	Play REC file (black loop).
3	Turn on the power.
4	Select play key.
5	Press MENU.
6	Press left key to select play OK.
7	Select START OK.
8	Show word of slide show on LCD display.
9	Test.

Test Mode	Mode 2: REC
1	Setup EUT and PC as shown on 1.4.
2	The lens of EUT was covered with black tape.
3	Turn on the power of all equipment.
4	Press REC key.
5	Save black file.

Test Mode	Mode 3: USB LCD on
1	Setup EUT and PC as shown on 1.4.
2	Loop transmit REC file with USB cable.
3	Turn on the power.
4	Write DSC file to PC for example.

Test Mode	Mode 4: Preview
1	Setup EUT and PC as shown on 1.4.
2	The lens of EUT was covered with black tape.
3	Turn on the power of all equipment.
4	Select capture preview mode.
5	Test.