

# Impinj, Inc.

701 N. 34th Street, Suite 300 Seattle WA 98103 USA  
TEL: +1-206-834-1116 Fax: +1-206-517-5262

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046

Attention: Application Examiner / Review Engineer

Subject: Request to change in identification per section 2.933 of FCC rules

Date: 2015-06-24

Reference: FCC ID: **MAD-RU00-M03**

To The Commission:

This Change of Identification request applies for a new FCC ID: TWYIPJRS2000 as established in 47CFR 2.933(b) for a currently approved device. This application by Impinj, Inc. will establish a new FCC ID under Impinj, Inc. grantee code for purpose of marketing. The original grant to **Microelectronics Technology Inc.** will remain in effect.

An authorization letter by **Microelectronics Technology Inc.** is attached.  
Per 2.933(b)

1. The original identification is **MAD-RU00-M03**
2. The original grant date is **04/29/2015**
3. The equipment is electrically identical, only the FCC ID number is different.
4. The original test results are applicable and representative of this changed device.
5. Exterior photographs are included in this application.

The following files are electronically submitted as attachments:

**Cover Letter**

**External Photos**

**FCC ID label format and location**

Sincerely yours,



-----  
Name: Bill Ashley

Impinj, Inc.

Tel: +1-206-834-1116

Fax: +1-206-517-5262

E-mail: ashley@impinj.com