

FCC ID on Equipment - MT410 and MT410G PLB (and amendment thereof)

ATTENTION: We have become aware that pursuant to Section 2.926(d), the slash mark (/) is not allowed for use within the FCC Identifier, and “that the equipment product code assigned by the grantee shall consist of a series of Arabic numerals, capital letters or a combination thereof, and may include the dash or hyphen (-) only.”

We respectfully request that our previously entered ID being:

TXJMT410/410G

be amended to:

TXJMT410-G

so as to comply with Section 2.926(d)

In anticipation of this amendment being agreeable to the FCC, we have provided images of the corrected FCC ID on our equipment. Note the location of this ID is identical for both the MT410 and GPS equipped variant MT410G.



Placement of “FCC ID: TXJMT410-G”