



Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5590MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		







Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5670MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	3		
Test Voltage	DC 3.3V (through jig via Notebook PC)		







Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	III
		Frequency	TX 5755MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3









**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11n-HT40	UNII Band	III
		Frequency	TX 5795MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)			3









Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

# Antenna: Omni-S Antenna

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	I
		Frequency	TX 5180MHz
Cable Loss	1.4dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		






Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5200MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	I
Cable Loss	1.4dB	Frequency	TX 5240MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		









Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5260MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5300MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2A
Cable Loss	1.4dB	Frequency	TX 5320MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		








Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5500MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		






Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5580MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		







Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	II-2C
Cable Loss	1.6dB	Frequency	TX 5700MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)	0		
Test Voltage	DC 3.3V (through jig via Notebook PC)		









Audix Technology Corp.  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City 244, Taiwan

Tel: +886 2 26099301  
Fax: +886 2 26099303

Test Date	2017/10/02~18	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	III
Cable Loss	1.6dB	Frequency	TX 5745MHz
Simultaneous Factor 10 log(n) (Note: "n" is antenna number)		Test Voltage	DC 3.3V (through jig via Notebook PC)
			0





**Audix Technology Corp.**  
No. 53-11, Dingfu, Linkou, Dist.,  
New Taipei City244, Taiwan

**Tel: +886 2 26099301**  
**Fax: +886 2 26099303**

Test Date	2017/10/02	Temp./Hum.	24°C/53%
Mode	802.11a	UNII Band	III
		Frequency	TX 5785MHz
Cable Loss	1.6dB	Test Voltage	DC 3.3V (through jig via Notebook PC)
Simultaneous Factor 10 log(n) (Note: “n” is antenna number)	0		

