

Carestream Health, Inc. 150 Verona Street Rochester, NY 14608

> To: Curtis-Straus LLC Certification Department 527 Great Road Littleton, MA 01460

Object: 15.247 equipment without connector at the transmitter output.

We, CARESTREAM HEALTH INC, manufacturer of the KODAK RVG6500 System, attest that, the design of our equipment can't allow a conducted measurement of the carrier transmitter. No output connector for the antenna and no specific test point for the antenna are available in the WiFi circuitry portion. Only radiated measurements of the transmitter power can be realized on the KODAK RVG 6500 System.

Regards,

Ronald L. CAIN

**EMC** Compliance Engineer