

www.alereon.com | 10800 Pecan Park Blvd. | Suite 100 | Austin,Tx 78750 | 512.345.4200 | 512.345.4201

To whom it may concern,

The AL5808 Octal module is too small for attaching an FCC identification label. Instead, the following statements will be added to the User's Manual. In addition, the same statements will be printed on a sticker and adhered to the packaging for each module that is shipped.

"This device contains FCC ID U9YAL5808. This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:(1) This device may not cause harmful interference.(2) This device must accept any interference received, including interference that may cause undesired operation. "

Thanks,

Parmveer Singh Director of Systems Applications Alereon, Inc.

3/22/2021

3/22/2021 CONFIDENTIAL 1 of 1