Appendix C. Photographs of Setup

Conducted Emission

Mode 1



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F17C Page No. : C1 of C5
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01

Report No. : FR783112



SIDE VIEW

Mode 2



FRONT VIEW


SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F17C Page No. : C2 of C5
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01






REAR VIEW



SIDE VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F17C Page No. : C3 of C5
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01





Radiation Emission

Mode 1-6



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F17C Page No. : C4 of C5
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01



Mode 7-15

FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 FCC ID: UCVHSTNH-F17C Page No. : C5 of C5
Report Issued Date : Oct. 11, 2007
Report Version : Rev. 01