



Cisco Meraki
500 Terry A Francois Blvd. 4th Floor
San Francisco, CA 94158
T 415.432.1000
F 415.632.5899

Federal Communications Commission
7435 Oakland Mills Road
Columbia MD 21046

Subject: Letter of Attestation

FCC ID: UDX-60026010
Model: MR18-HW


We, **Cisco Systems, Inc.** declare this equipment has channel selection/operation algorithms to comply with FCC rules when radio 1 and radio 3 transmit simultaneously in 2.4GHz mode, and when radio 2 and radio 3 transmit simultaneously in 5GHz mode.

The **Meraki MR18 (MR18-HW)** wireless access point firmware will take the following actions to ensure RF compliance within FCC regulations:

- (a) Rely on an algorithm coded in our firmware to avoid concurrent same-channel transmission of radio 1 and radio 3, and radio 2 and radio 3.
- (b) Rely on an algorithm coded in our firmware to eliminate servicing 802.11 clients on the Radio 3. Thus there will be no broadcasting of SSID or timer-based beacon frames. This will preclude the need for action (a) described above in all known operational cases.
- (c) Power reduction settings are not customer adjustable. Tools exist for customer configuration via Meraki Dashboard to reduce the power beyond the required reduction. Please see other attestation/filing documents related to SDR and radio configuration control /country setting for more information.

Radio 3's primary function is as a scanning radio. It has rare to occasional transmissions. Meraki Access Point firmware is optimized by design to eliminate simultaneous same-band transmission, as it would be detrimental to Radio 2 function.

Sincerely,

A handwritten signature in blue ink, appearing to read 'BC', is positioned above a horizontal dashed line.

Benjamin Calderon / Vice President, Operations and Hardware

TEL: 415-432-1000

FAX: 415-632-5899

E-mail: compliance@meraki.com