

Correspondence by Project

Project Number:

[1977480606](#)

Correspondence Number	Memo
UGP-WSW001-1	<p>1) The two-condition statement contained in section 15.31(a)(3) of the FCC rules does not appear on the device label. Per section 15.31(a)(5), when the device is so small that it is not practicable to put this statement on the device, it can alternatively be placed in the instruction manual. Please submit either a revised label, or a revised user's manual, with the statement included. Response: A photo has been taken to show the unit is smaller than a person's hand and also the owner's manual has been revised to include the FCC statement.</p> <p>2) The schematic diagrams submitted are incomplete. Please submit the full set of schematics Response: The Schematics have been revised.</p> <p>3) The FCC ID printed on the example label is "UGP-W5W001", which does not match the FCC ID on the rest of the application. Please correct the label, or if the label is correct, please submit the application with the correct identifier. Response: The FCC ID has been revised to show the correct FCC ID.</p> <p>4) Based on the submitted duty cycle plots, the on-time used for the duty cycle calculation is incorrect. Please correct. Response: The duty cycle information has been revised to show the correct calculation.</p>