

**dward**

---

**From:** dward [dward@atcb.com]  
**Sent:** Friday, December 19, 2008 2:29 PM  
**To:** 'Yoshinobu.Asai@jp.ul.com'  
**Cc:** 'customerservice@atcb.com'  
**Subject:** www.AmericanTCB.com ATCB007120 | UJHNR21263AF39508 | 662K - NR2123AF395 | | UJHNR21263AF39508\_ATCB007120

Regarding [www.AmericanTCB.com](http://www.AmericanTCB.com) application:

ATCB ID: ATCB007120

FCC ID: UJHNR21263AF39508

IC: 662K - NR2123AF395

TCF:

Account name: Yoshi

Please note the following issues and respond as soon as possible.

- 1 The receiver application portion is confusing. There is not operational description of the WB receiver (assumed to mean Weather Band). Part of the information indicates this is a scanning receiver (page 8 of the 15B test report), yet the required information for certification of a scanning receiver has not been provided or is not readily observable in the existing documentation.
- 2 Please provide an adequate operational description of the receiver.
- 3 If this is a scanning receiver, please provide the required information as follows: show how tuning control prevents user adjustability and frequency selection, provide an attestation that the device cannot tune in the cellular bands.
- 4 If this is a scanning receiver then the label must contain a statement 'warning against modifications to allow cellular reception'. I do not see this on the label sample.
- 5 If this is a scanning receiver then the equipment code would be CSR not CXX. Please fully explain and correctly identify the proper equipment code.
- 6 If this is not a scanning receiver, please clearly identify what the receiver function is.

In order to finish the application review, I will need answers to the above issues.

Thank you for choosing American TCB for your certification needs.

*Dennis Ward*

Director of Engineering

American TCB

Certification Resource for the Wireless Industry [www.atcb.com](http://www.atcb.com)

703-847-4700 fax 703-847-6888

direct - 703-880-4841