

ATCB ID: ATCB004367
FCC ID : UMP650
Account name: aidclab

Item	Question	Answer	Remark
(2)	There is a large difference in peak data from previous report. Please explain if modifications were made. Note the report cites no modifications were made. If so, please provide detail or explanations for the large difference in result	AIDC had been added a resistance(R14) in the remote controller that was shown in the attached schematic. The resistance value is 1.8k ohm. AIDC uses the resistance to reduce the output power, that resistance doesn't affect other function.	The update location are shown in File name: <u>Schematic(T1).pdf</u>