



08 May 2008  
Ref: US-000185

To FCC

BABT  
Balfour House, Churchfield Road  
Walton on Thames  
Surrey, KT12 2TD  
United Kingdom  
Telephone: +44 (0)1932 251200  
Fax: +44 (0)1932 251201  
Direct Dial: +44 (0)1932 251261  
E-mail: Vina.Kerai@babt.com  
Website: www.babt.com

**Overall Assessment Letter for GD852P**  
**FCC id: UPMFW390001**

I have reviewed this application and find it compliant.

This is an application for a fixed wireless phone which supports GSM 850 and PCS 1900. The phone additionally supports GSM 900 and DCS 1800, however are not relevant as they are not supported in North America.

Please note the following:

1: Label

The label initially contained an incorrect FCC ID and was therefore updated to state the correct FCC ID.

2: User Manual

The user manual was requested to be updated to include the statements contained in Part 15.19(a)(3), this was subsequently corrected.

3: Test Report

The Part 15B test report did not initially contain the conducted emissions N-Line and L-Line plots. The report has been corrected and supplied for submission.

I underwent the FCC RF exposure training at BABT in July 2007.

Yours sincerely

Vina Kerai  
Compliance Engineer, BABT

