

7. Labelling Instructions

WCM-9116 label (Figure 11) is to be applied to top of RS9116W-DB00-CC0 (Figure 10) See Figure 12. J1 of PCBA (Figure 13)

Figure 10 RS9116W-DB00-CC0 Top



Figure 11 WCM-9116 Label




Figure 12 RS9116W-BD00-CC0 labeled WCM-9116

