

Huf Korea Co., Ltd., FCC ID: URT26-013-500 & URT26-010-500 , Assessment NO.: AN07T6972 and AN07T6973 Notice#1 [Inbox](#)

★ from **"tim.dwyer@ccsemc.com"** <tim.dwyer@ccsemc.com>

[hide details](#) 7:58 pm (0 minutes ago)

[Reply](#)

to geoffrey.do@sgs.com

cc tim.dwyer@ccsemc.com

date Jul 5, 2007 7:58 PM

subject Huf Korea Co., Ltd., FCC ID: URT26-013-500 & URT26-010-500 , Assessment NO.: AN07T6972 and AN07T6973 Notice#1

Dear Geoffrey,

Q1: This item is for information only and no corrective response is required. For 125 kHz devices, FCC 15.209 specifies the use of an average detector. The test report measurements were made with a Q.P. detector. In this case it can be concluded that the levels from the Q.P. detector would be higher than with the average detector, so there is no risk of non-compliance. In the future, please include an explanation in the test report when a detector is used that is not the one specified in the rules.

Best regards,

Tim Dwyer

CCS Technical Reviewer

Huf Korea Co., Ltd., FCC ID: URT26-010-500, Assessment NO.: AN07T6973, Notice#1 [Inbox](#)

★ **"tim.dwyer@ccsemc.com"** to Geoffrey

[show details](#) Jul 7 (2 days ago)

[Reply](#)

Dear Geoffrey,

I missed one item in this application. There was no FCCID label and location exhibit. There was a label exhibit for URT26-013-500, but not for URT26-010-500. Please send the exhibit.

Thank you and best regards,

Tim Dwyer

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information within 30 days of the original e-mail date may result in application dismissal and forfeiture of the filing fee. Also, please note that partial responses increase processing time and should not be submitted. Any questions about the content of this correspondence should be directed to the e-mail address listed below the name of the sender.

[Reply](#) [Reply to all](#) [Forward](#) [Invite tim.dwyer@ccsemc.com to Gmail](#)

★ **"Do, Geoffrey (Gunpo)" <Geoffrey.Do@sgs.com>** to tim.dwyer [show details](#) Jul 8 (18 hours ago)



[Reply](#)

Dear Tim,

I'm sending you the document(FCC ID Label) again.

Please check the Label.

If you have any question, please send email.

Best Regards

Geoffrey.

=====
SGS Testing Korea Co., Ltd.
Wireless Div. RF Lab
Engineer Geoffrey Do / [/ geoffrey.do@sgs.com](mailto:geoffrey.do@sgs.com)
18-34, Sanbon-dong, Gunpo-si, Gyeonggi-do, Korea. 435-040
Tel:+82(0)31 428 5745 Fax:+82(0)31 427 2371 Mobil:+82(0)10 9089 9387
"SGS is the world's leading inspection, verification, testing and certification company"
www.electrolab.kr.sgs.com

- Show quoted text -

Information in this email and any attachments is confidential and intended solely for the use of the individual(s) to whom it is addressed or otherwise directed. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of the Company.
Finally, the recipient should check this email and any attachments for the presence of viruses. The Company accepts no liability for any damage caused by any virus transmitted by this email.
All SGS services are rendered in accordance with the applicable SGS conditions of service available on request and accessible at http://www.sgs.com/terms_and_conditions.htm

HUF-BHKRFH FCC ID Label Rev.1.pdf
118K [View as HTML](#) [Download](#)