


Report No.: FA322304-07

Appendix D. SAR Test Setup Photos


<With Scanner>



Right Cheek With Battery 1




Right Tilted With Battery 1




Left Cheek With Battery 1



Left Tilted With Battery 1




Right Tilted With Battery 2




Left Cheek With Battery 2

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : D1 of D4 Report Issued Date: Aug. 14, 2013 Report Version : Rev. 01




Back With Battery 1,
Test Separation 1.5 cm




Report No.: FA322304-07


Back With Battery 1+ Headset, Test Separation 1.5 cm



Back With Battery 2, Test Separation 1.5 cm



Back With Battery 1, Test Separation 1 cm




Back With Battery 2, Test Separation 1 cm




Back With Battery 1+ Holster, Test Separation 0 cm

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : D2 of D4
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01



Bottom Side With Battery 1, Test Separation 1 cm




Report No.: FA322304-07

Top Side With Battery 1,
Test Separation 1 cm




Left Side With Battery 1,

Test Separation 1 cm



Right Side With Battery 1, Test Separation 1 cm




Front With Battery 1,
Test Separation 1 cm

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : D3 of D4
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01

FCC SAR Test Report

<Without Scanner>




Right Tilted With Battery 1




Report No.: FA322304-07

Left Cheek With Battery 1



Back With Battery 1, Test Separation 1 cm



Back With Battery 1, Test Separation 1.5 cm

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55AH Page Number : D4 of D4
Report Issued Date : Aug. 14, 2013
Report Version : Rev. 01