





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(850band _CH 188)







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(850band_CH 251)







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Active mode_4.2V

Antenna Polarization H(850band _CH 128)






Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm





0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(850band _CH 188)






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(850band_CH 251)






Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Idle mode_3.5V
Antenna Polarization H






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m





87.0 dBuV/m





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m





87.0 dBuV/m





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Idle mode_4.2V
Antenna Polarization H






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m





87.0 dBuV/m





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m



87.0 dBuV/m







Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Active mode_3.5V

Antenna Polarization H(1900band _CH 512)






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm




0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm





0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(1900band _CH 661)






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm





0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(1900band _CH 810)







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Active mode_4.2V

Antenna Polarization H(1900band _CH 512)







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24



FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(1900band _CH 661)






Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm





Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm





0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization H(1900band _CH 810)







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8





Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm




0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Antenna Polarization V







Taiwan ETS Product Service Co., Ltd.

Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm



0.0 dBm





Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

0.0 dBm





0.0 dBm





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Idle mode_3.5V
Antenna Polarization H(1900band)






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m



87.0 dBuV/m






Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8

87.0 dBuV/m



Antenna Polarization V

72.0 dBuV/m






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

72.0 dBuV/m



87.0 dBuV/m






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m





87.0 dBuV/m





Report Number: W6M20802-8869-P-22/24
FCC ID: V3H-B8

Idle mode_4.2V
Antenna Polarization H(1900band)






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m



87.0 dBuV/m






Report Number: W6M20802-8869-P-22/24


FCC ID: V3H-B8

87.0 dBuV/m



Antenna Polarization V

72.0 dBuV/m






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

72.0 dBuV/m



87.0 dBuV/m






Taiwan ETS Product Service Co., Ltd.


Report Number: W6M20802-8869-P-22/24

FCC ID: V3H-B8

87.0 dBuV/m



87.0 dBuV/m



Up Line: PK Limit Line

Down Line: Ave Limit Line

Note:

1. The plots are pre-scanned data for determining the tested points and for reference only.
2. The exact test result is shown in the data table of Radiated emission test of this test report.