

T: 519.745.8887 F: 519.745.9774 www.intellimec.com

Statement for Change in Identification Pursuant to Section 2.933 of FCC Rules

This statement is regarding change in the identification of previously certified equipment as required by section 2.933 of the FCC rules.

A change in the FCC identifier is requested pursuant to paragraph (a) of the 2.933 of the FCC rules. We certify that there has been no change in the in the design, circuits or construction of the original equipment.

Furthermore, in accordance with the requirements of paragraphs (b).1 to 5 of this section we state that:

- 1. Original Identification used prior to change request is FCC ID: POOWML-C40
- 2. The data of original grant is: 01 May, 2006.
- 3. The equipment bearing new identification is not different from the original equipment.
- 4. The original test results will continue to be representative of and applicable to the equipment bearing changed identification.

The new for this equipment FCC ID : V57ILABSN01

Regards,

Inam Rahim H/W Design Engineer