




Internal Photos



FCC ID: V7L300301







Old and new detectors with RF boards installed



The differences are:

1. The shape of the RF board was changed.
2. The antenna form was slightly changed.
3. Piezo sounder not populated.
4. A new detector head is being used.